

OAKVILLE

Map 4
2017 Signalized Intersections
Level of Service (PM Peak Hour)

- Level of Service A to C (average vehicle delay 0 to 35 seconds)
- Level of Service D (average vehicle delay 36 to 55 seconds)
- Level of Service E & F (average vehicle delay 56 seconds or higher)
- Non-Oakville Signal (Halton, MTO)
- Water Features

N

May 2018

Strategic Business Services
Community Development Commission

S:\DEPARTME\Engineering and Construction
\State of Infrastructure Update