




Tree Inventory Notes


Tree No.	Common Name	Botanical Name	DBH (CM)	Cond.	Comments	Recommendation
673	Black Walnut	Juglans nigra	39	F	Volunteer tree	Retain
676	Norway Maple	Acer platanoides	44	F/G		Retain
677	Norway Maple	Acer platanoides	75	F		Retain
678	Norway Maple	Acer platanoides	68	F	CODIT. Minor deadwood in canopy	Retain
679	White Spruce	Picea glauca	22	F		Remove due to Construction
680	White Spruce	Picea glauca	19	F		Remove due to Construction
681	White Spruce	Picea glauca	26	F		Remove due to Construction
682	White Spruce	Picea glauca	18	F	Past insect damage evident	Remove due to Construction
683	White Cedar	Thuja occidentalis	20	F	Trunk split; Healed over	Remove due to Construction
684	White Cedar	Thuja occidentalis	16	F	Trunk split; Healed over	Remove due to Construction
685	White Cedar	Thuja occidentalis	17	F	Trunk split; Healed over	Retain
686	Scots Pine	Pinus sylvestris	28	F		Remove due to Construction
687	Scots Pine	Pinus sylvestris	29	F		Retain
688	Sugar Maple	Acer saccharinum	117	F	Moderate deadwood in canopy	Retain
689	Sugar Maple	Acer saccharinum	78	F		Retain
690	Norway Maple	Acer platanoides	32	F	Shallow exposed roots. Minor deadwood in canopy.	Remove due to Construction
691	Norway Maple	Acer platanoides	63	F	Shallow exposed roots. Minor deadwood in canopy. Showing girdling.	Retain
692	Norway Maple	Acer platanoides	42	F		Remove due to Construction
693	Norway Maple	Acer platanoides	52	F	Slight lean. Interfering with hydro lines. Minor deadwood in canopy.	Retain
694	Littleleaf Linden	Tilia cordata	16	F/G	Interfering with hydro lines.	Retain
695	Norway Maple	Acer platanoides	75	F	Exposed roots. Minor deadwood in canopy.	Retain

1 Tree Inventory
SK-1 Scale 1:300

3171 Lakeshore Road West
Town of Oakville

LEGEND

-  Plant Identification Key
-  Existing Coniferous Tree
-  Existing Deciduous Tree



SK-1

DATE: July 10, 2017

SCALE 1:300