

Terraprobe

Consulting Geotechnical & Environmental Engineering Construction Materials Inspection & Testing

September 29, 2021.

File No. 1-17-0348 **Brampton Office**

Town of Oakville Planning Services Department 1225 Trafalgar Road Oakville, Ontario L6H0H3

LETTER OF RELIANCE RE: **UPDATED PHASE ONE ENVIRONMENTAL SITE ASSESSMENT** 70 OLD MILL ROAD, OAKVILLE, ONTARIO

To whom it may concern,

We are the authors of the report entitled,

UPDATED PHASE ONE ENVIRONMENTAL SITE ASSESSMENT 70 OLD WLL ROAD OAKVILLE, ONTARIO File No.: 1-17-0348-41.1, September 28, 2021

in reference to the above-noted property. Terraprobe Inc. (Terraprobe) prepared the referenced Report (the "Report"), for the sole use and benefit of 2317511 Ontario Inc., (our client) for the referenced Project, subject to the general limitations noted in the report. At the request of our Client, in order to support and facilitate, the Project, and subject to the terms of this letter, Terraprobe hereby authorizes "Town of Oakville Planning Services Department and the Region of Halton Planning and Legal Services," to use and rely upon the Report to the same extent and in the same manner as if it had been addressed to the Relier at the time of its issuance.

The Report was prepared in accordance with applicable, customary and generally accepted professional and technical standards ordinarily exercised by other engineering professionals providing similar services under similar circumstances in the location and at the time the subject services were provided and the Report prepared. Terraprobe makes no representations or warranties regarding compliance with any other standard(s). Town of Oakville Planning Services Department and the Region of Halton Planning and Legal Services' reliance upon the Report is subject in all respects to this letter, the conditions and limitations set forth in the Report and Terraprobe's General Terms and Conditions applicable to the Report. The use of the Report constitutes acceptance of the foregoing.

It should be noted that the Report is representative of the site conditions at the time of the field investigation (September 22, 2021). We cannot comment on any changes that may have occurred to the site subsequent to our site investigation and are not responsible for any implications thereof. Any use of the Report is subject to the general limitations noted in the Report. The Report may not be used for purposes other than those expressly stated in the Report.

Reliance on and/or use of the Report constitutes acceptance of the foregoing, and the terms and limitations noted in the subject Report.

Yours truly,

Terraprobe Inc.

Samuel Oyedokun, P. Eng., PMP, QPEsA Associate

Shama M. Qureshi, P. Eng., P. Geo., QPRA-ESA Principal, Head of Environmental Engineering Division