


Note:
For tree assessment completed
for road crossing, see Figure 10B

Tree Retention Status	
1400	Tree ID - Trees to be removed for trail/swale construction
1400	Tree ID - Trees within 5m of the trail/swale construction disturbance
1400	Tree ID - Trees that are outside of disturbance zone and there not impacted
X	Trees to be removed for trail/swale construction
X	Trees within 5m of the trail/swale construction disturbance
X	Trees that are outside of disturbance zone and there not impacted
X	Dead Trees



Legend			
	NHS Limit		Dripline Limit
	Core 11 Boundary		Regional Floodline Limit
	Existing Contour Elevation		Stable TOB
	Trail (Including limit of disturbance)		Surveyed TOB
	Proposed Grade		Creek Centreline
	Existing Grade		Option 2 Road Limit of Disturbance
	Trail Segment Label		Trees Within This Area Were Studies As Part Of Road Assessment. See Section 10
	Trail Segment Break		

Stonybrook Consulting Inc.
David Schaeffer Engineering Ltd.
Bird and Hale Limited
R.J. Burnside and Associates Limited
LGL Limited
GEO Morphix Ltd.
J.F. Sabourin and Associates Inc.

MATTAMY PHASE 3 ADDENDUM TO THE JOSHUA'S CREEK TRIBUTARIES EIR/FSS
DRAWING 11
TREE ASSESSMENT ALONG TRAIL/SWALE
MAY 2020